

Platinum Glass

Application instructions

Application must take place above 5 degrees celsius in a well ventilated area, we recommend wearing protective gloves. Do not dilute.

Surface condition is important, ensure it is dry, free of any waxes, oils & silicones. The surface should be thoroughly clayed & wiped with a 50% ratio of isopropyl alcohol and water.

Apply three to four drops onto the lint free applicator pad provided, spread the coating evenly from top to bottom in sections. Bonding begins immediately, remove excess within a few minutes with a light wipe of a microfibre cloth. One applicator per window is recommended.

We recommend two coats to increase durability, please leave 1 hour before the second coat.

The coating will fully cure within 12 hours, try to avoid using the wipers until fully hardened.

For optimum performance, clean the wipers with an IPA mix.

This coating requires no special maintenance, after the glass has been fully sealed the coating will last 6-8 months dependent on wiper use. Coating durability is improved when wipers are limited in use and the glass is cleaned only with car shampoo, PH neutral snow foams and citrus degreaser's. Avoid high PH cleaners and TFR's.

Remove sealant that comes into contact with, window rubbers, trim and paintwork immediately.

Caution:

Avoid contact with eyes & skin. Do not ingest. Refit cap tightly after use.

